




HP Pavilion ze4530US CD Rom Replacement

Replace a CD Rom that is not capable of reading discs.

Written By: Sonny Sem




Step 1 — CD Rom



- Unscrew three screws from under the keyboard. The keyboard must be removed for this process.

Step 2



- After the screws have been removed, use one finger to push the CD Rom out while the other hand is simultaneously pulling the CD Rom out.

Step 3



- The CD Rom has been successfully taken out.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-18 04:08:44 AM.